PRODUCT ENGINEERING

PUBLISHED MONTHLY

McGRAW-HILL PUBLISHING COMPANY, INC. 330 West 42d Street, New York, N. Y.

INDEX TO VOLUME 4

January to December, 1933

January 1-40
February 41-80
March 81-120
April 121-160
May 161-200
June 201-240
July 241-280
August 281-320
September 321-360
October 361-400
November 401-440
December 441-480

*Illustrated

Abrasion and wear on materials *211

Aeronautics:

All metal plane *222
Beechcraft airplane *47
Boening fast transport plane *167
Curtiss-Wright airplane *405
Douglas airliner *367
Gerard Vultee plane *405
Heath Center wing plane *447
Hydraulic throttle control *46
Organized engineering makes the Macom. G. F. Nordenholt *122
Orion transport plane *447
Seversky all metal amphibian *285
Sperry automatic aircraft pilot.....*229
Trend of modern design *405
Wright airplane engines *166
Air compressor, free piston *7

Air Conditioning:

Automobile, air conditioned 329
Gear drive for air conditioning railroad car generator *229
Humidifier nozzle, self-cleaning.....*48
Humidity control *8
Portable motor driven humidifier.....*250
Railway air conditioner *129
Room coolers *228
Air tools, Kipp—product case history.....*59
Alloys, corrosion resisting 370
Alumilite for coloring 287

Aluminum:

Beer barrel *250
Coins of aluminum 127
Violin of aluminum *181
American Society for Testing Materials—meeting 152
American Society of Mechanical Engineers—annual meeting 32

Appearances and Finishes:

Appearance no substitute for quality. Hieber, Armstrong 190
Art versus engineering design. J. H. Daun 392
Case histories in product design. Maloney & Switzer.....*58, *106, *140, *305, *335
Colored plastics. F. E. Brill..... 297
Designing for the eye. F. E. Brill.... *16
Fine appearance without complications. W. D. Teague *462
Initial wear. R. E. W. Harrison *452
Relative value of appearance varies.. 273
Surface finishes *208

Applied Mechanics:

Safe loads for needle bearings (Ref. Bk. Sheets) *359
Shifting mechanisms for gears and clutches .....pt. 1 *298; pt. 2 *330
Autoclaves, new. L. L. Lunenschloss..... 471
Auto heater, Lucas—product case history.*107

Automobiles:

Air conditioned automobile 329
Air steering for automotive vehicles..*227
Dymaxion car *336
Reo self shifting transmission.....*226
Streamlined automobiles 394
Trends in automobile design *26; pt. 2 *70

Bakelite for flashlights *166
Bars, stresses in curved. H. F. Bariffi.... *68
Beams, stresses and deflections in built up. C. O. Sandstrom.....*365

Bearings:

Anti friction bearing mountings. Adam Fredericks *178, *224, *256
Applications of small rollers for bearings. K. L. Herrmann.....*138
Ball bearing mountings for high speed spindles. F. A. Firnhaber..pt. 1 *322; pt. 2 *383
Cost of friction measured 114
Gyroscope bearing *48
Gyroscope bearings. A. E. Schein.... *2
Hot acid pump bearings. F. A. Westbrook *188
Improved closures for anti friction bearings. A. M. Wasbauer.....*418
Safe loads for needle bearings (Ref. Bk. Sheets) *359
Track rollers have bearing seals. A. E. Palmer *390
White metal bearing alloys 153
Beer container *167
Beer kegs, bonderized 286

Belts:

Designing V-belt drives. Albert Hack. *53
Transmission ration and slip of V-belts. C. A. Norman *375
Beryllium copper for tools 165
Bimetal elements, thermostatic. H. D. Matthews *420
Bolts and nuts—new standards 233
Photoelastic analysis of threaded connections. A. G. Solakian *261
(Ref. Bk. Sheets) 199; erratum 232
Book reviews..... 38, 118, 158, 198, 238, 278, 318, 358, 398, 438, 478
Boring machine *47
Bottle crowner 47
Bottles for milk made of Opax..... 127
Bottling machine *411

Brakes:

Shock absorbers and brakes for knitting machines *226

Buses:

Streamlined bus *366
Bushings connection to aluminum disk. J. S. Carpenter *428

Calculator *416
Camera, midget *431
Camera for aerial mapping *416

Cams:

Built-up cam "Unicams" 48
Cam profiles for minimum inertia shocks. R. V. Hopkins *174
Equations for the design of involute cams. F. W. Shaw *131
Graphical analysis of cam roller mountings. E. C. Shanks.....*251, *350
Impact and wear on cams 218
Case histories in product design. Maloney & Switzer.....*58, *106, *140, *180, *305, *335

Castings:

Chemical finish for die castings..... 270
Concerning alloy steel castings..... 467
Die castings of light weight 223
Getting the most out of die castings.. *61
New uses for cast iron 152
Six competitive types of castings. D. Basch *282
Zinc alloys for die castings. W. M. Peirce *263
Zinc die castings for strength and wear 212
Castype machine *10
Century of Progress *247
Ceramics soldered to metals . J. E. Mateer *25
Chains, calculating sag in suspended. W. W. Johnson *28
Chicago World's Fair, see Century of Progress.

Chrome and chrome nickel iron alloys. T. H. Nelson..pt. 1 *258; pt. 2 *292; pt. 3 340
Chronolog, National Acme Co.—product case history *108
Clipper, hair, electric *287

Clutches:

Application of friction clutches to clamp adjuster *100
Cone clutch shifting mechanism. A. Smallwood *148
Magnetic clutches. C. Q. Payne *468
Shifting mechanisms for gears and clutches. Adam Fredericks..... pt. 1 *298; pt. 2 *330; pt. 3 *378
Cocobola substitute. C. F. Scribner..... 471
Color response of photocells. R. C. Hitchcock *465
Condensers for steam power plants..... 205
Control, magnetic. Porter Strother.....*423

Corrosion:

Metals selected for their resistance to corrosion *203
Properties of corrosion resisting alloys 370
Resistance of stainless clad welded sheets. W. J. Wachowitz *268
Cotton feeding system *328
Counting device. Vincent Waitkus *390
Coupling, rubber *102
Creep or plastic flow of metals..... 220
Creep resistance data 312
Crusher for road work *411

Dairy equipment *203
Defroster for electric refrigerators..... 47

Design, Calculations and Examples:

Allowable unit stress of different gear materials at various velocities (Ref. Bk. Sheets) 399
Autotram uses rubber in various places. F. L. Haushalter *362
Ball bearing mountings for high speed spindles. F. A. Firnhaber..pt. 1 *322; pt. 2 *383
Cam profiles for minimum inertia shocks. R. V. Hopkins *174
Castype design *10
Chart for determining the true angle between sides of hoppers (Ref. Bk. Sheets) *119
Decoration must be appropriate. J. W. Gosling *266
Dished heads of pressure vessels. C. O. Sandstrom *426
Engineering standards for the design of springs. W. M. Griffith.....*242
Engineering the design of welded products—symposium *82
Equations for the design of involute cams. F. W. Shaw *131
Gear thrust for 14½ deg. spur gears (Ref. Bk. Sheets) 400
Graphical analysis of cam roller mountings. E. C. Shanks.....*251
Graphical determination of shaft deflections. J. S. Carpenter *303
Graphical solutions for helical gear problems. J. K. Olsen *372
Gyroscope bearings. A. E. Schein... *2
Horsepower capacities of spur gears (Ref. Bk. Sheets)..pt. 1 39; pt. 2 79
Horsepower capacities of straight bevel gears (Ref. Bk. Sheets)..pt. 1 239; pt. 2 319
Hydraulic vs. mechanical feed. A. L. DeLeeuw pt. 1 .....*442
Initial wear. R. E. W. Harrison *452
Knitting machines adapt Jacquard principle from looms. R. H. Lawson *18
Minimum pitch diameter of spur gears (Ref. Bk. Sheets) 440
Modulus of section at angle α *479
"New things during the depression" 73
Organized engineering makes the Macom. G. F. Nordenholt.....*122
Pressure sensitive elements for gages and instruments. W. R. Clendinning.*143
Relation between pitch, pitch diameter and number of teeth 439

Standard practice instructions. R. F. Hanford 162
Typical designs of safety gears..... *104
Detents, retaining and locking. Adam Fredericks ..... pt. 2 *14
Diaphragms for gages and instruments. W. R. Clendinning *143
Dictaphone *431
Dichead unsymmetrical for increase capacity *288
Dihedral angle determined (Ref. Bk. Sheets) 119
Dimensions of machinery. R. M. Bigler *431
Dished heads of pressure vessels. C. O. Sandstrom *426
Dodge, William W. *114

Drawings:

Accuracy with slide rule. E. J. Carter 311
Broad versus narrow lettering. W. S. Brown 67
Drafting room procedures. H. L. Lackman *148
Draftsmen and their feelings. P. Bonsall 308
Dawing the ellipse. H. E. Gottlieb. *309
Quality of drawings. C. D. Haedrich 30
Record of titles. H. L. Lackman.... *431
Recording drawing changes. W. S. Brown *150
Recording drawing changes. H. L. Lackman *67
Value of old drawings 309
Dredger bucket *49
Drink mixer, Greene—product case history *60

Drives:

Designing V-belt drives. Albert Hack. *53
Gear drive for air conditioning railroad car generator *229
Spinning frame drive 328
Transmission ratio and slip of V-belts. C. A. Norman *375
Worm gear efficiency. J. C. Brewster 169
Dry cleaning equipment *328
Dump wagon, hydraulic, mounted on Caterpillar *103
Duplicating machine, Ditto—product case history *305
Dyeing equipment *206

Editorials:

Destructive complex 41
It's fun to paddle in shallow waters 81
Commodity prices 281
Don't hang around your own back yard 321
Engineering is not a game 361
New deal, new products 321
Oppose plans to limit equipment buying 361
Pioneering in 1933 1
Professional development 401
Shout it from the housetops 401
There is no magic in Engineers Council for Professional Development... 441
Time for drastic change 281
Electrical equipment, patents for. R. C. Muir 255
Electroplating and corrosion 207

Engineers and Engineering:

Art and engineering. A. J. A. Peterson 66
Extending engineering employment.... 352

Engines:

Airplane engine of 2.15 lb..... *222
Marine engines 130
Welded diesel engine crankcases..... *327
Wright airplane engines *166
Erosion-resistant materials *209
Escalator step *8
Evaporators and extractor baskets..... *207
Extractor baskets and evaporators..... *207

Fastenings. F. W. Shaw 392
Fastenings, shrink-fit. J. E. Hyler..... 471
Fastenings, sleeve, right and wrong. A. L. Foreman *310
Fastenings, wire locks and snap rings or Adam Fredericks *454
Feed, hydraulic vs. mechanical. A. L. DeLeeuw pt. 1 ..... *442
Film projector for demonstration..... *180
Foam avoided by compressed air. J. E. Hyler 269
Forming machine, cold roll *449
Fountain with lighting control..... *100
Frequency changers, built in *47
Furniture ornaments. C. F. Schribner.... 430

Gears:

Allowable unit stress of different gear materials at various velocities (Ref. Bk. Sheets) 399
Designing mongrel gears. C. A. Wiken. *311
Gear generators—patents. A. L. Stewart 254
Gear problem. Manious Gottlieb *350
Gear problem. C. W. Hinman..... *393
Gear problem. W. W. Johnson..... *350
Gear thrust for 14½ deg. spur gears (Ref. Bk. Sheets) 400
Geared drive for axle generator..... *229
Gears for varying torque loads. S. L. Crawshaw *188
Generator for cutting gears at one step up *6
Graphical determination of worm gear contact. W. M. Pohl *42
Graphical solutions for helical gear problems. J. K. Olsen *372
Horsepower capacities of spur gears (Ref. Bk. Sheets)..pt. 1 39; pt. 2 79
Horsepower capacities of straight bevel gears (Ref. Bk. Sheets) pt. 1 239; pt. 2 319
Lateral worm. F. B. Faulkner..... *393
Locating gear center. J. G. Real, H. C. Zimmerman *29
Minimum pitch diameter of spur gears (Ref. Bk. Sheets) 440
Relation between pitch, pitch diameter and number of teeth (Ref. Bk. Sheets) 439
Safety gears. F. W. Shaw..... *189
Shifting mechanisms for gears and clutches..pt. 1 *298; pt. 2 *330, pt. 3 *378
Solutions to the gear problem. Hobart, Wickstrand, Strom *391, Shaw, Wilder *429
Strength of undercut teeth. Hans Schemm *265
Types of gears and their mountings. P. C. Day *337
Typical designs of safety gears..... *104
Undercut gear teeth. Hans Schemm.. *469
Worm gear efficiency. J. R. Sawyer 230
Generating unit with single wing 49
Grinder *102
Grinder, with aluminum housing..... *406

Hammer attachment for power shovels.. *329
Handles, detailing. E. C. Shanks..... *191
Hardness: comparison of hardness scales and tensile strength—erratum..... 31
Heater, electric *414
Hopper, coal *414

Industrial control (ed) 241
Initial wear. R. E. W. Harrison *452

Iron:

Abrasion resistance of cast iron..... 312
New alloy cast iron 313
Chrome and chrome nickel iron alloys. T. H. Nelson...pt. 1 *258; pt. 2 *292; pt. 3 *340
Corrosion resistant cast iron 353
Iron *141
Ironer, Westinghouse *7

Jacquard principle applied to knitting machines. R. H. Lawson *18
Job tickets, daily. J. S. Archer..... *151

Knitting machines *449
Knitting machine, full-fashioned, brakes and shock absorbers *226
Knitting machines adapt Jacquard principle from looms. R. H. Lawson *18
Knitwear Industrial Exposition 113

Laminated metals. G. A. Ruehmling.... *369
Laminated molded materials, phenolic (table) 460
Lamp base *228
Lathe with built in motor drive *128
Lathes, patents for. J. E. Lovely..... 255
Lighting control for Buckingham fountain. *100
Linkages for transport mechanisms. F. R. Zimmerman *56
Lock, magnetic 5

Locomotives:

Electric *192
Materials for locomotives *216
Streamlined locomotives *403
Triple expansion locomotive *404
Looms, patents for. Albert Palmer..... 254

Lubrication:

Motor with low oil consumption..... *270

Machinery:

After designing—what? C. F. Cowdry, Jr. 387
Charts showing how manufacturers have improved their products..407, 408
Magnesium for tokens 127
Manufacturing—development procedure ... 417

Materials:

Chrome and chrome nickel iron alloys. T. H. Nelson..pt. 1 *258; pt. 2 *292; pt. 3 340
Die castings *61
Erosion resistant materials *209
Experiments on materials for elastic elements 192
High stresses, impact and fatigue.... *215
Laminated metals. G. A. Ruehmling. *369
Mechanical design of thermostatic bimetal elements. H. D. Matthews.. *420
Metals for reflectors. R. C. Roetger... 137

Metals selected for their resistance to corrosion *203
New material uses 100
Photoelectric analysis of threaded connections. A. G. Solakian *261
"Powdered metals" *9
Properties of phenolic laminated molded materials (table) 460
Service under high temperatures *219
Service under high temperatures. G. C. McCormick 349
Six competitive types of castings. D. Basch *282
Soldered ceramics. J. E. Mateer.... *25
Symposium at meeting of Technical Assn. of Pulp & Paper Industry.. 113
Types of plastics and their properties. H. M. Richardson *456
Wear and abrasion *211
Weight as an important factor..... *221
What price quality? F. D. Miner.... *300
Zinc alloys for die castings. W. M. Peirce *263

Mechanisms and Constructions:

Anti friction bearing mountings. Adam Fredericks *178, *224, *256
How photo-electirc controls are applied.....pt. 1 *345; pt. 2 *380
Improved closures for anti friction bearings. A. M. Wasbauer *418
Linkages for transport mechanisms. F. R. Zimmerman *56
Quick release mechanism. G. A. Fries. *111
Retaining and locking detents. Adam Fredericks .....pt. 2 *14
Wire locks and snap rings for fastenings. Adam Fredericks *454

Metals:

Abrasion and wear *211
Chrome and chrome nickel iron alloys. T. H. Nelson.....pt. 1 *258; pt. 2 *292; pt. 3 340
Copper lead bearing bronzes 272
Erosion resistant materials..... *209
High stresses, impact and fatigue.... *215
Laminated metals. G. A. Ruehmling.. *369
"Powdered metals" *9
Selected for their resistance to corrosion *203
Service under high temperatures..... *219
Weight as an important factor..... *221
Micromation study of machines reveal defects 394
Milling machine with 10-built in motors. *446
Mixing machine, gas heater *412
Motorcycle, German *286

Motors:

Control and protection of motors, pt. 1 *332; pt. 2. Porter Strother.... *423
Driving equipment for spinning yarn.. 128
Selecting the motor to fit the requirements.....pt. 1 *342; pt. 2 *388
Mower, McCormick-Deering *127

Nails, holding power of 22
Nails protected with lead heads 127
New materials and parts....34, 74, 115, 158, 194, 234, 274, 314, 354, 396, 434, 474
New Products exhibition 233
Numbering wheel redesigned. F. R. Lufkin. *109

Oil burner *448
Oil heaters—fine appearance without complications. W. D. Teague *462
Oil-o-matic *413
Opax for milk bottles 127

Parts and Units:

Air steering for automotive vehicles.. *227
American standard bolts and nuts (Ref. Bk. Sheets) 199; erratum 232
Anti friction bearing mountings. Adam Fredericks.....178, *224, *256
Control and protection of motors, pt. 1 *332; pt. 2. Porter Strother..... *423
Designing V-belt drives. Albert Hack.. *53
Gear drive for air conditioning railroad car generator *229
Getting the most out of die castings.. *61
"Powdered metals" *9
Proportions and tolerances for punched holes. J. K. Olsen *185
Radially tapered steel disk springs. W. W. Boyd *63
Reo self shifting transmission *226
Room coolers *228
Selecting the motor to fit the requirements.....pt. 1 *342; pt. 2 *388
Six competitive types of castings. D. Basch *282
Small rollers for bearings. K. L. Herrmann *138
Three types of photocells *289
Transmission ration and slip of V-belts. C. A. Norman *375
Types of gears and their mountings. P. C. Day *337
Well rounded stampings economical. J. K. Olsen *50
Worm gear efficiency. J. C. Brewster.. 169
Pasteurizer, welded stainless *250

Patents:

Avoiding duplication in development work: gear generators, textile looms, power specialties, electrical equipment, automatic lathes 254
Phenolic laminated molded materials (table) 460
Photoelastic analysis. A. G. Solakian.... *450
Photoelastic analysis of threaded connections. A. G. Solakian *261
Photoelastic measurements. Solakian & Beyer *145
Photoelastic tests. A. G. Solakian *171

605
v. 4

Photo-Electric Cells:

Cell for reversing "dye jigg" 47
Color response of photocells. R. C. Hitchcock *465
Concerning photo-electric control. Joseph Clark *348
Control for press 129
Counting device *429
Dry disk type photo-electric cells.. R. T. Pierce 348
How photo-electric controls are applied .....pt. 1 *345; pt. 2 *380
Humidity control for rayon 129
Invisible stars detected by photocells. 352
Photo-electric anemometer *471
Maximum shear stresses. P. N. Bland 351
Protection for oil burners..... 329
Three types of photocells *289

Pipes:

Lead alloy pipes 368
Pipes and fittings, materials for..... 204

Plastics:

Canvas-bonded Bakelite valve *8
Colored plastics. F. E. Brill 297
Properties of phenolic laminated molded materials (table) 460
Types of plastics and their properties. H. M. Richardson *456
Plating, cadmium 101
Plating, mist 24
Poisson's ratio 31, 109
Polariscope for stress analysis. Solakian & Beyer *145
Power Show *32
Press for tolerances 193
Press with electric driven pump..... *407
Pressure sensitive elements for gages and instruments. W. R. Clendinning... *143
Pressure vessels heads. C. O. Sandstrom.. *426
Prism, moment of inertia of a, about the axis a-a (Ref. Bk. Sheets)..... 159
Problem analysis. L. A. Trofimov..... 135
Product development survey *402
Product developments....5, 46, 127, 165, 226, 247, 285, 327, 366, 402, 446
Product Engineering—historical summary.. 1
Production stock chart. G. W. Aufmuth.. *392
Pulleys, attaching light. A. M. Mann..... *310

Pumps:

Rotary pump using wobble plate action *366
Rotary pump with rotors of novel form *101
Turbine pumps 286

Quality, what price? D. F. Miner..... *300

Radio *288
Air King midget product case history *106
Midget radio. Colonial Radio—product case history *307
Smaller radio tubes 448

Railway Cars:

Autotram uses rubber in various places. F. L. Haushalter *362
Budd two unit stainless steel train.. *446
Burlington streamlined train *446
Rail cars of light weight 221
Rubber mountings 285
Streamlined, air conditioned aluminum rail car *5
Subway cars mechanically ventilated. *367
Ratchet, high speed. E. J. White..... *270
Reel for cable *287

Reference Book Sheets:

Allowable unit stress of different gear materials at various velocities.... 399
American standard bolts and nuts 199; erratum 232
Chart for determining the true angle between sides of hoppers *119
Gear thrust for 14½ deg. spur gears 400
Horsepower capacities of spur gears. pt. 1 39; pt. 2 79
Horsepower capacities of straight bevel gears .....pt. 1 239; pt. 2 319
Minimum pitch diameter of spur gears 440
Modulus of section at angle a..... *479
Moment of inertia of a prism about the axis a-a..... 159
Relation between pitch, pitch diameter and number of teeth 439
Safe loads for needle bearings..... *359
Tables for calculating helical type springs 279
Reflectivity of commercial surfaces..... 231
Reflector metals. R. C. Roetger..... 137

Refrigerators:

Electric *182
Materials for refrigeration equipment 205
Reinvention. Hellmund. Shelmire 309

Research and Development:

Development procedure in manufacturing 417
Product development and research. L. A. Trofimov 23
Rods, calculating connecting clearance of. W. W. Johnson *268
Roller, convertible road *127

Rubber:

Autotram uses rubber in various places. F. L. Haushalter *362
Rubber lined drums for acid containers 127
Rubber rugs 127
Rule of rubber. H. Kilborn..... 230

Salt and pepper shakers. Reynolds Spring—product case history *306
Sander, portable belt *7
Scale, bathroom, Detecto — product case history *306
Scale, Toledo—product case history *58
Scoops *410
Scooter, Skippy—product case history.... *335
Screw fastenings, blind *102
Shaft deflections. A. W. Fischer..... *428
Shaft deflections, graphical determination of. J. S. Carpenter *303
Shaft twist. J. S. Carpenter 232
Shaker, cocktail, electric *413
Shovel, electric *46
Shovel, power *410
Shovel dipper *48
Sink of pressed steel *168
Sizing device *406
Smoke-density meter *6
Soldered ceramics. J. E. Mateer..... *25
Sound chart 177

Spindles:

Ball bearing mountings for high speed spindles. F. A. Firnhaber..pt. 1 *322; pt. 2 *383
Spindle for sander of carbon alloy steel.. *407

Springs:

Engineering standards for the design of springs. W. M. Griffith *242
Flexible spring connection prevents vibration in scale *103
Hysteresis in spiral springs 272
Radially tapered steel disk springs. W. W. Boyd *63
Spring stresses, index and other factors. Frederick Franz 308
Stresses for springs. W. M. Griffith.. 349
Tables for calculating helical type springs (Ref. Bk. Sheets)..... 279

Stampings:

Well-rounded stampings economical. J. K. Olsen *50

Standardization:

American standard bolts and nuts (Ref. Bk. Sheets) 199; erratum..... 232
Ball bearings and charts for lantern slides approved 114
Definitions for pressure and vacuum gages 192
Engineering standards for the design of springs. W. M. Griffith..... *242
Gear tooth form and abbreviations for engineering terms 73
New bolt and nut standards 233
Rotating air cylinders and adapters.. 33
Solutions to the gear problem..... *392
Sound chart 177
Standard practice instructions. R. C. Hanford 162
Tables for calculating helical type springs (Ref. Bk. Sheets)..... 279
Tapered roller bearing standards.... 273

Steel:

Alloy steels for machine tools..... 219
Corrosion resistance of stainless-clad welded sheets. W. J. Wachowitz..*268
Grain size chart for classification of steels 193
Reflectivity of enameled steel. C. J. Phillips 310
"Slide rule" chart for alloy steels.. 272
Stellite and nitriding for wear resistance 213
Tests on steel forgings in Germany.. 272
Two ply stainless. S. L. Ingersoll.. 134
Veneered steel panels 313
Steering, air, for automotive vehicles....*227
Sterilizer *416
Stock chart, production. G. W. Aufmuth.. *392

Stresses:

Curved disks stresses. C. J. Phillips..*231
Material requirements for high stresses, impact and fatigue *215
Maximum shear 351
Stress calculations, shrink-fit. A. G. Solakian *171
Stress, shear, in machine elements. A. H. Beyer..... 390
Stresses analyzed with polariscope. Solakian & Beyer *145
Stresses and deflections of test fixture. F. H. Frey *269
Switch, built in flow *229
Switches, wax operated 152
Tank, milk *286
Tanks for foods and chemicals..... *205
Taps, chromium plated. J. Vincent..... 349
Telephone dial, splash proof *48

Theoretical Analysis:

Calculating dihedral angles. R. E. Hughes *269
Calculation for twist of shafts. J. S. Carpenter 232
Calculating sag in suspended chains. Constructing tangents. H. F. Baraffi *28
Cam roller mountings. E. C. Shanks..*251
Circumferential adjustments. J. E. Hyler *308
Constructing tangents. H. F. Baraffin *28
Developing the cone. I. Cohen..... *110
Dihedral angles. C. E. Lewis..... *190
Engineering small products. L. N. Stewart *66
Graphical analysis of impact in mechanical movements—Klein's construction *67
Hopper problem. D. E. Hobart..... *349
Laying out reverse curves. D. E. Hobart *271
Laying out reverse curves. Hans Schemm *271
Locating gear center. J. G. Real, H. C. Zimmerman *29
Methods of solving a problem in triangles. Shaw, Strott, Johnson.... *111
Moment of inertia of a prism about the axis a-a (Ref. Bk. Sheets)... 159
Problem in triangles. F. W. Shaw.... *31
Solutions to problem in triangle. Latshaw, Kligman 149
Solution to the reverse curve problem. N. M. Wickstrand *231
Stresses in the lifting hasp. N. M. Wickstand *110
Thermos server *142
Thermostat case *416
Thermostat for refrigerator motor..... 128
Thermostatic bimetal elements. H. D. Matthews *420
Throttle control, hydraulic *46
Toaster *141
Tolerances and proportions for punched holes. J. K. Olsen *185
Tower truck *368

Tractors—Caterpillar model 70 tractor.... *168
Transfer action timed. F. Server..... *393
Transformers, hermetically sealed..... 46
Transmission, electro-hydraulic *49
Transmission, Reo self shifting *226
Triangle problem. Schemm, Wiken, Cavagnet, Prion, Johnson *470
Triangles, right. F. Oyen..... *431
Tubing, streamlined. E. C. Hartmann.... *464
Turbine at Vasteras, Sweden *101
Type-casting machine *10

Valves:

Canvas-bonded Bakelite valve *8
Tungsten carbide for valve stems and seats 353
Ventilation for subway cars *367
Vibration absorption by flexible spring.... *103
Vibration as a fire hazard 153
Violin of aluminum *181
Visualette demonstrator *180

Waffle iron *141
Washing machines *140, *414
Water dispensing cabinet *288
Waterwheel, Pelton, of stainless steel.... 49
Weigher, dynamic *130
Weighing with photo controls. W. A. Weckerly *468

Welding:

Better designs with less welding. A. P. Wood *91
Constant strength structures. Everett Chapman *94
Designing for automatic welding. E. W. P. Smith *86
Designing is a four dimension problem. R. E. Kinkead 90
Engineering the design of welded products—symposium 82
Flame cutting and gas welding. D. E. Roberts *85
Machine tools built of rolled steel. R. T. Hazelton *95
Rolled steel for the welded product. H. G. Marsh *82
Specifications for welded products. H. E. Stitt *88
Tank type welder for railroad maintenance *165
Vibrations of structures and materials. W. M. Pohl *91

Wheels:

Locomotive wheel center *103
Railroad 102
Wheels and pulleys—anti friction bearing mountings. Adam Fredericks.. *178, *224, *256
Wiring combination with seven styles of wall plates 6

Zinc alloys for die castings. W. M. Peirce..*263

AUTHORS

ARCHER, J. S. Daily job tickets.....*151
Amstrong, G. C. Appearance no substitute for quality 190
Aufmuth, G. W. Production stock chart..*392

BARAFFI, HERBERT F. Simple method for constructing tangents..... *28
Stresses in curved bars..... *68
Basch, D. Six competitive types of castings.*282
Beyer, Albin H. Shear stress in machine elements 390
Beyer, A. H., and A. G. Solakian. How stresses are analyzed with a polariscope *145
Bigler, R. M. Common sense in dimensions.*431
Blank, P. N. Maximum shear stresses.... 351
Bonsall, P. Draftsmen and their feelings... 308
Boyd, W. W. Radially tapered steel disk springs *63
Brewster, J. C. What to specify for high efficiency worm drives 169
Brill, F. E. Colored plastics 297
Designing for the eye *16
Brown, W. S. Broad versus narrow lettering 67
Drawing changes *150

CARPENTER, J. S. Flanges connections to aluminum disks *428
Graphical determination of shaft deflections *303
Simplified calculation for twist of shafts 232
Carter, E. J. Greater accuracy with the slide rule 311
Chapman, Everett. Constant strength structures *94
Clark, Joseph. Concerning photo electric control *348
Clark, W. R. Design it right 188
Clendinning, William R. Pressure sensitive elements for gages and instruments *143
Cohen, I. Developing the cone *110
Cowan, E. Allowable unit stress of different gear materials at various velocities (Ref. Bk. Sheet) 399
Gear thrust for 14½ deg. spur gears (Ref. Bk. Sheets) 400
Cowan, S. Minimum pitch diameter of spur gears (Ref. Bk. Sheets)..... 440
Relation between pitch, pitch diameter and number of teeth (Ref. Bk. Sheets) 439
Cowdry, C. F., Jr. After designing—what? 387
Crawshaw, S. L. Gears for varying torque loads *188

DAM, JOHN H. Art versus engineering design 392
Day, P. C. Types of gears and their mountings *337
De Leeuw, A. L. Hydraulic vs. mechanical feed, pt. 1 ..... *442

FAULKNER, FRANK B. Lateral worm..*393
Firnhaber, F. A. Ball bearing mountings for high speed spindles..pt. 1 *322; pt. 2 *383
Fischer, A. W. Shaft deflections by the method of elastic weights..... *428
Foreman, A. L. Right and wrong fastenings *310
Franz, Frederick. Spring stresses, index and other factors 308
Fredericks, Adam. Retaining and locking detents, pt. 2 ..... *14
Typical anti friction bearing mountings *178, *224, *256
Shifting mechanisms for gears and clutches..pt. 1 *298; pt. 2 *330; pt. 3 *378
Wire locks and snap rings for fastenings *454
Freeman, R. A. Klein's construction..... *67
Frey, F. H. Preloading to reduce deflections *269
Fries, George A. Quick release mechanism.*111

GOSLING, J. WOODLEY. Decoration must be appropriate *266
Gottlieb, H. E. Drawing the ellipse.... *309
Gottlieb, Manious. Gear problem *350
Griffith, W. M. Engineering standards for the design of springs *242
Spring design 349
Tables for calculating helical type springs (Ref. Bk. Sheets)..... 279
Grill, C. H. Horsepower capacities of spur gears (Ref. Bk. Sheets)..., pt. 1 39; pt. 2 76
Horsepower capacities of straight bevel gears (Ref. Bk. Sheets).. pt. 1 239; pt. 2 319

HACK, ALBERT. Charts, tables, data for designing V-belt drives..... *53
Haedrich, C. D. Concerning quality of drawings 30
Hanford, Raymond C. Standard practice instructions 162
Harrison, R. E. W. Initial wear *452
Hartmann, E. C. Elements of streamline sections *464
Haushalter, F. L. Rubber parts for various purposes *362
Hazelton, R. T. Machine tools built of rolled steel *95
Hellmund, R. E. Re-invention and the younger engineer 309
Herrmann, K. L. Applications of small rollers for bearings *138
Hieber, George E. Appearance no substitute for quality 190
Hinman, C. W. Answering all letters helps restore confidence 428
Gear problem *393
Hitchcock, R. C. Color response of photocells *465
Hobart, Dean E. Civil service problem... *148
Hopper problem *349
Laying out reverse curves *271
Solutions to the gear problem..... *391
Hopkins, R. V. Cam profiles for minimum inertia shocks *174
Hough, C. W. Photoelectric anemometer.*471
Houser, A. M. Power specialties 255
Hughes, R. E. Calculating dihedral angles.*269
Hyler, John E. Circumferential adjustments *308
Compressed air to avoid foam..... 269
Shrink-fit fastenings..... 471

INGERSOLL, S. L. Designing with two ply stainless 134

JOHNSON, W. W. Calculating connecting rod clearance *268
Calculating sag in suspended chains.. *28
Gear problem *350
Methods of solving a problem in triangles *112

KILBORN, HOLLOWAY. Rubber rules . 230
Kinkead, Robert E. Designing is a four dimension problem 90
Kligman, A. R. Solution to problem in triangles 150

LACKMAN, H. L. Drafting room procedures *148
Record of drawing titles *431
Recording drawing changes *67
Lange, Leo F. American standard bolts and nuts (Ref. Bk. Sheets) 199; erratum 232
Latshaw, Elmer. Solutions to problem in triangles 149
Lawson, Robert H. Applying the Jacquard to knitting machines *18
Lewis, C. E. Problem in dihedral angles..*190
Lovely, J. E. Automatic lathes 255
Lufkin, Fred R. Redesign of a small assembly *109
Lunenschloss, L. L. New autoclaves.... 471

MALONEY, T. J., and GEORGE SWITZER. Case histories in product design ..*58, *106, *140, *180, *305, *335
Mann, A. M. Attaching light pulleys..... *310
Marsh, H. G. Rolled steel for the welded product 82
Mateer, J. E. Soldered ceramics..... *25
Matthews, H. D. Mechanical design of thermostatic bimetal elements.. *420
McCormick, G. C. Materials that merit recognition 349
Miner, D. F. What price quality?..... *300
Muir, R. C. Electrical equipment..... 255

NELSON, R. C. Unnecessary waste.... 431
Nelson, T. Holland. Chrome and chrome nickel iron alloys..pt. 1 *258; pt. 2 *292; pt. 3 340
Nordenholt, George F. Organized engineering makes the Macom *122
Norman, C. A. Transmission ratios and slip of V-belts *375

OLSEN, J. K. Gaphical solutions for helical gear problems..... *372
Proportions and tolerances for punched holes *185
Why well rounded designs make economical stampings *50
Oyen, F. Right triangles *431

PALMER, A. E. Bearing seals in track rollers *390
Textile looms 254
Payne, C. Q. Magnetic clutch *468
Peirce W. M. Four zinc alloys for die castings *263
Petersson, A. J. A. Art and engineering.. 66
Phillips, C. J. Reflectivity of enameled steel 310
Stresses in curved disks *231
Pierce, R. T. Dry-disk type photo electric cells 348
Pohl, Walter M. Graphical determination of worm gear contact *42
Vibrations of structures and materials *91

RICHARDSON, H. M. Types of plastics and their properties *456
Roberts, D. E. Flame cutting and gas welding *85
Roetger, R. C. Metals for reflectors..... 137
Ruehmling, George A. Laminated metals. *369

SANDSTROM, C. O. Design of dished heads of pressure vessels..... *426
Stresses and deflections on a built up beam *365
Sawyer, J. R. Worm gear efficiency 230
Schein, Alexander E. Overcoming bearing deficiencies *2
Schemm, Hans. Laying out reverse curves.*271
Strength of undercut teeth *265
Undercut gear teeth *469
Scribner, C. F. Furniture ornaments..... 430
Substitute for cocobola..... 471
Server, F. Timed transfer action..... *393
Shanks, E. Chat. Detailing handles.... *191
Graphical analysis of cam roller mountings *251
Technicalities in nomenclature..... *350
Shaw, Francis W. Equations for design of involute cams *131
Fastenings 392
Methods of solving a problem in triangles *111
Problem in triangles *31
Safety gears *189
Solutions to the gear problem *429
Shelmire, Stanley R. Avoiding re-invention 309
Smallwood, A. Cone clutch shifting mechanism *148
Smith, E. W. P. Designing for automatic welding *86
Solakian, A. G. Scope of photo-elastic analysis *450
Tests check shrink fit stress calculations *171
Why threaded parts fail *261
Solakian, A. G., and A. H. Beyer. How stresses are analyzed with a polariscope *145
Stewart, A. L. Gear generators 254
Stewart, Lewis N. Engineering small products *66
Stitt, Harry E. Specifications for welded products *88
Strom, George A. Solutions to the gear problem *392
Strother, Porter. Magnetic control in the modern machine *423
Strott, J. F. Methods of solving a problem in triangles *111
Switzer, George, and T. J. Maloney. Case histories in product design..*58, *106, *140, *180, *305, *335

TEAGUE, WALTER DORWIN. Fine appearance without complications..*462
Trofimov, Lev. A. Engineering problems demand thinking in four directions 135, *183
Framing the questions to find the answer *183
Product development and research.... 23

VAN VOORHIS, M. G. Modulus of section at angle α (Ref. Bk. Sheets) *479
Moment of inertia of a prism about the axis a-a (Ref. Bk. Sheets)... 159
Vander Henst, A. Reflectivity of commercial surfaces 231
Vincent, J. Chromium plated taps 349

WACHOWITZ, W. J. Corrosion resistance of stainless-clad welded sheets.... *268
Waitkus, Vincent. Counting device..... *390
Wasbauer, Alfred M. Improved closures for anti friction bearings *418
Weckerly, W. A. Photo controls for weighing 468
Westbrook, F. A. Bearings in hot acid pump *188
White, E. J. High speed ratchet *270
Wickstrand, N. M. Analytical solution to the reverse curve problem..... *231
Safe loads for needle bearings (Ref. Bk. Sheets) *359
Solutions to the gear problem..... *391
Stresses in the lifting hasp..... *110
Wiken, C. A. Designing mongrel gears.... *311
Wilder, Arthur L. Solution to the gear problem *429
Wood, A. P. Better designs with less welding *91

YOEMANS, LUCIEN I. New products in old lines 189

ZIMMERMAN, F. R. Linkages for transport mechanisms *56